

www.emeraldnw.com

April 28, 2009

EPA Region 10 Solid Waste and Toxics Unit 1200 Sixth Ave, Suite 900 Seattle WA 98101 Attn: Dan Duncan

Recycling & Recovery

RE: Unmanifested Waste Report - Emerald Recycling

Dear Mr. Duncan;

Marine & Industrial Cleaning

Recycled Products

Waste Treatment & Disposal

Automotive Fluids Management

> Construction Services

Transportation Services

Vacuum Truck Services

Portable Storage

As you are aware, Emerald Recycling (Emerald) received a load of PCB contaminated oil from Purcell Equipment, 17227 Hwy 9, Snohomish, Washington. The attached information is being provided per the requirements for an unmanifested waste report under 40 CFR Part 761.211.

1) EPA Identification Number, Name and Address of the PCB Commercial Storage or Disposal Facility:

Temporary Storage:

Emerald Recycling 1500 Airport Way S. Seattle WA 98134 WAD 058 367 152

TSDF:

Clean Harbors (Aragonite), LLC 11600 N. Aptus Rd, Exit 56 Aragonite UT 84029 UTD 981 552 177

2) Date the commercial storage or disposal facility received the unmanifested PCB waste:

Unmanifested PCB waste was received on April 2, 2009 at Emerald Recycling. PCB waste was confirmed as regulated under TSCA on April 9, 2009 and April 14, 2009.

3) The EPA Identification Number, Name, and Address of the Generator and Transporter:

Generator:

Purcell Equipment 17227 Hwy 9

Snohomish WA 98296 EPA ID # WAH 000 032 066

USEPA REG

Transporter:

Emerald Services, Inc.

7343 East Marginal Way S.

Seattle WA 98108 WAD 058 364 647

4) A description of the Type and Quantity of the Unmanifested PCB Waste Received at the Facility:

850 gallons of PCB contaminated used oil contributing to contamination of approximately 9,000 gallons of used oil at the Emerald Recycling facility.

5) A Brief Explanation of Why the Waste was Unmanifested:

The generator was unaware that the used oil was contaminated with PCBs.

6) The Disposition Made of the Unmanifested Waste by the Commercial Storage or Disposal Facility:

The unmanifested waste was temporarily stored in tanks at the Emerald Recycling facility located on Airport Way in Seattle until disposal arrangements could be made for the waste. Of the original contaminated volume of approximately 9,000 gallons, 29,872 kg of contaminated oil and decontamination fluids were shipped from the Emerald facility on April 24, 2009. Currently, there are three totes (275 gallons each) of contaminated used oil with decontamination fluids and one drum of contaminated PPE and debris that are awaiting shipment to the permitted TSDF. All shipments coordinated by Emerald were, or will be, accompanied by a Uniform Hazardous Waste Manifest.

Emerald will provide a complete report to EPA regarding receipt, on-site management, and offsite shipment of this PCB contaminated used oil once all documents pertaining to the issue have been received. This report from Emerald will include details of PCB data, on-site decontamination of tanks, and copies of manifests and certificates of disposal from the TSDF (Clean Harbors). If you have any questions in the meantime, please feel free to contact me at the numbers below.

Sincerely,

Sheila Smith, Environmental Coordinator

Emerald Services, Inc.

(206) 832-3204 (Office)

(253) 370-7912 (Cell) (206) 832-3304 (fax)

sheilas@emeraldnw.com

cc: Facility Operating Record